

WATTMETER TRANSFER SWITCHES



3-PHASE, 3 CURRENT TRANSFORMERS, 3 CURRENT COILS - 3119C

Handle: Round Knurled

Jumpers supplied as shown

Engraving Code: 031D-2W14

DECKS	CONTACTS	POS.		
		OFF	*	ON
1	1 2 0 - - - - 1 3	X	X	X
	1 6 0 - - - - 1 5 1 7 0 - - - - 1 7	X	X	X
2	2 2 0 - - - - 2 3	X	X	X
	2 6 0 - - - - 2 5 2 7 0 - - - - 2 7	X	X	X
3	3 2 0 - - - - 3 3	X	X	X
	3 6 0 - - - - 3 5 3 7 0 - - - - 3 7	X	X	X



3-PHASE, 2 CURRENT TRANSFORMERS, 2 CURRENT COILS, 2 POTENTIAL COILS - 3120C

Handle: Round Knurled

Jumpers supplied as shown

Engraving Code: 031D-2W14

DECKS	CONTACTS	POS.		
		OFF	*	ON
1	1 2 0 - - - - 1 3	X	X	X
	1 6 0 - - - - 1 5 1 7 0 - - - - 1 7	X	X	X
2	2 2 0 - - - - 2 3	X	X	X
	2 6 0 - - - - 2 5 2 7 0 - - - - 2 7	X	X	X
3	3 2 0 - - - - 3 3	X	X	X
	3 6 0 - - - - 3 5 3 7 0 - - - - 3 7	X	X	X

